G-Core
Software Version 6.1.0

Release Notes

Dear business partners,

In the course of an update from G-Core to non-Geutebrück hardware, we would like to point out that the following information must be observed and checked!

For regular Windows 10 installations Intel® has changed the driver model to so-called DCH drivers. These are distributed via the Windows Update and are no longer compatible with the Intel® drivers previously used, so-called legacy drivers. The installation of a DCH driver is not reversible.

The new DCH drivers are used with the following Windows versions:

- Windows 10 1709
- Windows 10 1803
- Windows 10 1809
- Windows Server 2019

If a driver with **version 25.20.100.6444** or newer is installed on one of these systems, it is most likely a DCH driver. The exact version can be checked on the Intel® homepage.

The Geutebrück G-Core Installer contains drivers that are installed on all HW platforms known to us. However, these are legacy drivers. If a legacy driver is installed on a system with new drivers, this can cause lasting damage to your system.

Installations that use Geutebrück hardware or a Geutebrück system image are not affected, as Geutebrück uses a Windows Embedded version (Windows 10 1607). This version does not support the Intel® DCH drivers, so the legacy drivers included in the installation can still be used without restrictions.

Why do Geutebrück install drivers?

Specially tested drivers are installed by us to ensure maximum operational reliability and performance on platforms known to us.

How do I proceed with the installation?

Geutebrück has adapted the G-Core installation to the extent that it checks whether Windows 10 1709/1803 or 1809 are installed on the system and warns the user accordingly, the installation of the Intel® drivers is automatically deselected.

In this case our software will use the already installed new DCH driver. Of course the GPU acceleration is also available with the DHC drivers. If you notice any abnormalities or are unsure about the performance, please contact our service department.

If necessary, the driver version must be checked manually to see if a legacy driver is installed. Only then may the legacy driver be downgraded by the Geutebrück installer by selecting the driver package in the installer.

What do I have to consider after installing with DCH drivers? As a general rule, if G-Core software is run on your own hardware and Windows installations, you must check how performance and memory consumption are represented and change when Windows updates are performed.

This applies to all Geutebrück products that use GPU Intel® acceleration.

Further information about the drivers can be found on the following page:

https://www.intel.com/content/www/us/en/support/articles/000031 275/graphics-drivers.html

If you have any questions, the Geutebrück team is at your disposal via the hotline or service@geutebrueck.com.

G-Core Release 6.1.0

to show and reduce possible data loss. Improvement Axis Bodycam Adaptions of background process & icon Adaptions of background process & icon Adaption of the process & service names to create a uniform appearence. With this adaption it is no longer possible to insert the localhost or the localhost IP as a hostname for the Axis sodycam Axis Bodycam Administrator rights for user based folders With this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. Now it is possible to configure an encrypted connection between system controller and server Improvement Axis Bodycam Encrypted connection between system controller and server Improvement ANPR ANPR ANPR SDK update Bugfix MOS Misbehavior in MOS search An issue in the MOS was fixed, which led to a on non-specific exception in G-Core. Bugfix G-View G-View - SCS mode Bugfix G-Set Missing priority color of an event Axis Bodycam Misbehavior in PLC Simulator The PLC browser is now available again. Bugfix Axis Bodycam Misbehavior in saving video material Footage. Bugfix MBEG Misbehavior in amera cycles An issue with the MBEG plugin was fixed, which led to a worn op behavior of camera cycles. Bugfix Plugin E4 Plugin - H265 quality profile Custom quality profiles for H.265 now work correctly with the E4 plugin. Bugfix Cam Check Cam Check Report The images in the Cam Check Report The images in the Cam Check Report of the Axis bodycam integration was fixed, which led to a wrong behaviour of camera cycles. Bugfix Axis Bodycam Plugin E4 Plugin - H265 quality profile Custom quality profiles for H.265 now work correctly with the E4 plugin. Bugfix Axis Bodycam Setup saving not possible We fixed an issue, where a random number of bodycam plugins are not able to successfully save the respective of cotage. Bugfix Cam Check Cam Check Report The images in the Cam Check Report on whave the correct format. Axis Bodycam Incorrect description of BWC Connector An issue in the Axis Bodyca	ftware 1	Type	Short Description	Detailled Description
to show and reduce possible data loss. Improvement Axis Bodycam Adaptions of background process & icon Adaptions of background process & icon Adaption of the process & service names to create a uniform appearence. Improvement Axis Bodycam Administrator rights for user based folders Improvement Axis Bodycam Encrypted connection between system controller. With this adaption it is no longer possible to insert the localhost or the localhost IP as a hostname for the Axis system Controller. With this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. Now it is possible to configure an encrypted connection between the Axis System Controller and server Improvement ANPR ANPR SDK update Bugfix MOS Misbehavior in MOS search An issue in the MOS was frawd, which led to not detected movements in a selected area respective picture. Bugfix G-Set Misbehavior when importing old setups An issue with the import of old setups was fixed, which led to a an non-specific exception in G-Core. Bugfix G-Set Misbehavior in PLC Simulator An issue in the event configuration of G-Set was fixed, which led to a non visible priority color of a created event fixed. Bugfix Axis Bodycam Misbehavior in PLC Simulator The PLC browser is now available again. We fixed an issue, where a random number of bodycam plugins are not able to successfully save the respective footage. Bugfix MBEG Misbehavior in camera cycles An issue with the MBEG plugin was fixed, which led to a wrong behaviour of camera cycles. Bugfix Plugin E4 Plugin - H.265 quality profile Custom quality profiles for H.265 now work correctly with the E4 plugin. Bugfix Cam Check CamCheck Report The images in the CamCheck report now have the correct format. Axis Bodycam Incorrect description of BWC Connector An issue in the Axis Bodycam integration was fixed, which led to a wrong behaviour date of the Axis bodycam integration was fixed, which led to a wrong behaviour date afterwards. Bugfix Axis Body	<i>w</i> Feature F	Plugin	New E5 camera plugin	G-Core now supports the new Geutebrück E5 camera series.
Improvement Axis Bodycam Axis Bodycam Administrator rights for user based folders with this adaption it is no longer possible to insert the localhost or the localhost IP as a hostname for the Axis spotner with the modern and server. With this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. With this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. With this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. With this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. With this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. With this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. With this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. With this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. With this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. With this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. With this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. With this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. Whith this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. Whith this adaption it is no longer user lea	rovement F	Axis Bodycam	New logfile for user based folders	There is a new logfile in each user based folder which includes the current state of the saved and retrieved video footage to show and reduce possible data loss.
improvement Axis Bodycam Administrator rights for user based folders With this adaption it is no longer possible to view/change/delete the user based folders and its content without administrator rights. Now it is possible to configure an encrypted connection between the Axis System Controller and the G-Core ser Improvement ANPR ANPR SDK update This update includes stability and performance improvements as well as bug fixes. Please note: A service ANPR Wrapper) that supports the use of the 64-bit version has been removed. The functing integrated in the ANPR service. Bugfix G-Set Misbehavior when importing old setups An issue in the MOS was fixed, which led to not detected movements in a selected area respective picture. Bugfix G-Set Missensive was fixed of G-View -SCS mode When using the SCS mode in G-View, the buttons for MOS and Event were hidden in the timeline. This behavior fixed. Bugfix G-Set Missing priority color of an event An issue in the event configuration of G-Set was fixed, which led to a non visible priority color of a created event bugfix PLC Misbehavior in PLC Simulator The PLC browser is now available again. Bugfix Axis Bodycam Misbehavior in camera cycles An issue with the MBEG plugin was fixed, which led to a wrong behaviour of camera cycles. Bugfix Plugin E4 Plugin - H265 quality profile Custom quality profiles for H265 now work correctly with the E4 plugin. Bugfix Cam Check CamCheck Report The images in the CamCheck report now have the correct format. Bugfix Axis Bodycam Incorrect description of BWC Connector An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterward	rovement A	Axis Bodycam	Adaptions of background process & icon	Adaption of the process & service names to create a uniform appearence.
Improvement Axis Bodycam Encrypted connection between system controller and server Improvement ANPR ANPR SDK update This update includes stability and performance improvements as well as bug fixes. Please note: A service (ANPR Wrapper) that supports the use of the 64-bit version has been removed. The functing rated in the ANPR service. Bugfix MOS Misbehavior in MOS search An issue in the MOS was fixed, which led to not detected movements in a selected area respective picture. Bugfix G-Set Misbehavior when importing old setups An issue with the import of old setups was fixed, which led to a an non-specific exception in G-Core. Bugfix G-View G-View - SCS mode When using the SCS mode in G-View, the buttons for MOS and Event were hidden in the timeline. This behavior fixed. Bugfix G-Set Missing priority color of an event An issue in the event configuration of G-Set was fixed, which led to a non visible priority color of a created event Bugfix PLC Misbehavior in PLC Simulator The PLC browser is now available again. Bugfix MBEG Misbehavior in saving video material We fixed an issue, where a random number of bodycam plugins are not able to successfully save the respective footage. Bugfix Plugin E4 Plugin - H.265 quality profile Custom quality profiles for H.265 now work correctly with the E4 plugin. Bugfix Cam Check CamCheck Report The images in the CamCheck report now have the correct format. Bugfix Axis Bodycam Incorrect description of BWC Connector An issue in the Axis BWC connector was fixed, which led to a urrong behaviour during the export of the VMS configuration file. Bugfix Axis Bodycam Playback problem of video material An issue in the hinstallation of the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards. Bugfix Axis Bodycam Playback problem of video material An issue in the hinstallation of the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards.	rovement A	Axis Bodycam	Localhost address no longer usable as hostname	With this adaption it is no longer possible to insert the localhost or the localhost IP as a hostname for the Axis system controller.
improvement ANPR ANPR Discovered and server This update includes stability and performance improvements as well as bug fixes. Please note: A service (ANPR Wrapper) that supports the use of the 64-bit version has been removed. The funcintegrated in the ANPR service. Bugfix MOS Misbehavior in MOS search An issue in the MOS was fixed, which led to not detected movements in a selected area respective picture. Bugfix G-Set Misbehavior when importing old setups An issue with the import of old setups was fixed, which led to a non-specific exception in G-Core. Bugfix G-Set Missing priority color of an event An issue in the event configuration of G-Set was fixed, which led to a non visible priority color of a created event fixed. Bugfix G-Set Missing priority color of an event An issue in the event configuration of G-Set was fixed, which led to a non visible priority color of a created event bugfix PLC Misbehavior in PLC Simulator The PLC browser is now available again. Bugfix Axis Bodycam MBEG Misbehavior in camera cycles An issue with the MBEG plugin was fixed, which led to a wrong behaviour of camera cycles. Bugfix Plugin E4 Plugin - H.265 quality profile Custom quality profiles for H.265 now work correctly with the E4 plugin. Bugfix Cam Check CamCheck Report The images in the CamCheck report now have the correct format. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis BWC connector was fixed, which led to a urong behaviour during the export of the VMS configuration file. An issue in the installation of the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards. An issue in the installation of the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards. An issue in the installation of the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards.	rovement A	Axis Bodycam	Administrator rights for user based folders	
Please note: A service (ANPR Wrapper) that supports the use of the 64-bit version has been removed. The functintegrated in the ANPR service. Bugfix MOS Misbehavior in MOS search An issue in the MOS was fixed, which led to not detected movements in a selected area respective picture. Bugfix G-Set Misbehavior when importing old setups An issue with the import of old setups was fixed, which led to a an non-specific exception in G-Core. Bugfix G-View G-View - SCS mode When using the SCS mode in G-View, the buttons for MOS and Event were hidden in the timeline. This behavior fixed. Bugfix G-Set Missing priority color of an event An issue in the event configuration of G-Set was fixed, which led to a non visible priority color of a created event Bugfix PLC Misbehavior in PLC Simulator The PLC browser is now available again. Bugfix Axis Bodycam Misbehavior in saving video material We fixed an issue, where a random number of bodycam plugins are not able to successfully save the respective of footage. Bugfix MBEG Misbehavior in camera cycles An issue with the MBEG plugin was fixed, which led to a wrong behaviour of camera cycles. Bugfix Plugin E4 Plugin - H.265 quality profile Custom quality profiles for H.265 now work correctly with the E4 plugin. Bugfix Axis Bodycam Setup saving not possible We fixed an issue, where the G-Set setup was not saved successfully after a change of the Axis bodycam configuration file. Bugfix Axis Bodycam Crash in BWC Connector An issue in the Axis BWC connector was fixed, which led to an unwanted crash during the export of the VMS configuration file. Bugfix Axis Bodycam Incorrect description of BWC Connector An issue in the installation of the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards.	rovement A	Axis Bodycam	**	Now it is possible to configure an encrypted connection between the Axis System Controller and the G-Core server.
Bugfix G-Set Misbehavior when importing old setups An issue with the import of old setups was fixed, which led to a an non-specific exception in G-Core. Bugfix G-View G-View - SCS mode When using the SCS mode in G-View, the buttons for MOS and Event were hidden in the timeline. This behavior fixed. Bugfix G-Set Missing priority color of an event An issue in the event configuration of G-Set was fixed, which led to a non visible priority color of a created event bugfix PLC Misbehavior in PLC Simulator The PLC browser is now available again. Bugfix Axis Bodycam Misbehavior in saving video material We fixed an issue, where a random number of bodycam plugins are not able to successfully save the respective videotage. Bugfix MBEG Misbehavior in camera cycles An issue with the MBEG plugin was fixed, which led to a wrong behaviour of camera cycles. Bugfix Plugin E4 Plugin - H.265 quality profile Custom quality profiles for H.265 now work correctly with the E4 plugin. Bugfix Axis Bodycam Setup saving not possible We fixed an issue, where the G-Set setup was not saved successfully after a change of the Axis bodycam configuration file. Bugfix Axis Bodycam Crash in BWC Connector The images in the CamCheck report now have the correct format. Bugfix Axis Bodycam Incorrect description of BWC Connector An issue in the Axis BWC connector was fixed, which led to an unwanted crash during the export of the VMS configuration file. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards.	rovement A	ANPR	ANPR SDK update	Please note: A service (ANPR Wrapper) that supports the use of the 64-bit version has been removed. The functions are
Bugfix G-View G-View - SCS mode When using the SCS mode in G-View, the buttons for MOS and Event were hidden in the timeline. This behavio fixed. Bugfix G-Set Missing priority color of an event An issue in the event configuration of G-Set was fixed, which led to a non visible priority color of a created event Bugfix PLC Misbehavior in PLC Simulator The PLC browser is now available again. Bugfix Axis Bodycam Misbehavior in saving video material We fixed an issue, where a random number of bodycam plugins are not able to successfully save the respective videotage. Bugfix MBEG Misbehavior in camera cycles An issue with the MBEG plugin was fixed, which led to a wrong behaviour of camera cycles. Bugfix Plugin E4 Plugin - H.265 quality profile Custom quality profiles for H.265 now work correctly with the E4 plugin. Bugfix Axis Bodycam Setup saving not possible We fixed an issue, where the G-Set setup was not saved successfully after a change of the Axis bodycam configuration file. Bugfix Axis Bodycam Crash in BWC Connector An issue in the Axis BWC connector was fixed, which led to an unwanted crash during the export of the VMS configuration file. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards.	jfix N	MOS	Misbehavior in MOS search	An issue in the MOS was fixed, which led to not detected movements in a selected area respective picture.
fixed. Bugfix G-Set Missing priority color of an event An issue in the event configuration of G-Set was fixed, which led to a non visible priority color of a created event Bugfix PLC Misbehavior in PLC Simulator The PLC browser is now available again. Bugfix Axis Bodycam Misbehavior in saving video material We fixed an issue, where a random number of bodycam plugins are not able to successfully save the respective footage. Bugfix MBEG Misbehavior in camera cycles An issue with the MBEG plugin was fixed, which led to a wrong behaviour of camera cycles. Bugfix Plugin E4 Plugin - H.265 quality profile Custom quality profiles for H.265 now work correctly with the E4 plugin. Bugfix Axis Bodycam Setup saving not possible We fixed an issue, where the G-Set setup was not saved successfully after a change of the Axis bodycam configuration file. Bugfix Axis Bodycam Crash in BWC Connector An issue in the Axis BWC connector was fixed, which led to an unwanted crash during the export of the VMS configuration file. Bugfix Axis Bodycam Incorrect description of BWC Connector An issue in the installation of the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video afterwards.	gfix (G-Set	Misbehavior when importing old setups	An issue with the import of old setups was fixed, which led to a an non-specific exception in G-Core.
Bugfix PLC Misbehavior in PLC Simulator The PLC browser is now available again. Bugfix Axis Bodycam Misbehavior in saving video material We fixed an issue, where a random number of bodycam plugins are not able to successfully save the respective videotage. Bugfix MBEG Misbehavior in camera cycles An issue with the MBEG plugin was fixed, which led to a wrong behaviour of camera cycles. Bugfix Plugin E4 Plugin - H.265 quality profile Custom quality profiles for H.265 now work correctly with the E4 plugin. Bugfix Axis Bodycam Setup saving not possible We fixed an issue, where the G-Set setup was not saved successfully after a change of the Axis bodycam configuration. Bugfix Cam Check CamCheck Report The images in the CamCheck report now have the correct format. Bugfix Axis Bodycam Crash in BWC Connector An issue in the Axis BWC connector was fixed, which led to an unwanted crash during the export of the VMS configuration file. Bugfix Axis Bodycam Incorrect description of BWC Connector An issue in the installation of the Axis bodycam integration was fixed, which led to a wrong description of the apparterwards. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video	jfix (G-View	G-View - SCS mode	When using the SCS mode in G-View, the buttons for MOS and Event were hidden in the timeline. This behavior is now fixed.
Bugfix Axis Bodycam Misbehavior in saving video material We fixed an issue, where a random number of bodycam plugins are not able to sucessfully save the respective videotage. Bugfix MBEG Misbehavior in camera cycles An issue with the MBEG plugin was fixed, which led to a wrong behaviour of camera cycles. Bugfix Plugin E4 Plugin - H.265 quality profile Custom quality profiles for H.265 now work correctly with the E4 plugin. Bugfix Axis Bodycam Setup saving not possible We fixed an issue, where the G-Set setup was not saved sucessfully after a change of the Axis bodycam configuration. Bugfix Cam Check CamCheck Report The images in the CamCheck report now have the correct format. Bugfix Axis Bodycam Crash in BWC Connector An issue in the Axis BWC connector was fixed, which led to an unwanted crash during the export of the VMS configuration file. Bugfix Axis Bodycam Incorrect description of BWC Connector An issue in the installation of the Axis bodycam integration was fixed, which led to a wrong description of the appartnership. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video and the playback of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video material An issue in the Axis bodycam integration was fixed.	yfix (G-Set	Missing priority color of an event	An issue in the event configuration of G-Set was fixed, which led to a non visible priority color of a created event.
Footage. Bugfix MBEG Misbehavior in camera cycles An issue with the MBEG plugin was fixed, which led to a wrong behaviour of camera cycles. Bugfix Plugin E4 Plugin - H.265 quality profile Custom quality profiles for H.265 now work correctly with the E4 plugin. Bugfix Axis Bodycam Setup saving not possible We fixed an issue, where the G-Set setup was not saved sucessfully after a change of the Axis bodycam configuration. Bugfix Cam Check CamCheck Report The images in the CamCheck report now have the correct format. Bugfix Axis Bodycam Crash in BWC Connector An issue in the Axis BWC connector was fixed, which led to an unwanted crash during the export of the VMS configuration file. Bugfix Axis Bodycam Incorrect description of BWC Connector An issue in the installation of the Axis bodycam integration was fixed, which led to a wrong description of the appartment of the Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video material An issue in the Axis bodycam integration was fixed.	gfix F	PLC	Misbehavior in PLC Simulator	The PLC browser is now available again.
Bugfix Axis Bodycam Setup saving not possible We fixed an issue, where the G-Set setup was not saved sucessfully after a change of the Axis bodycam configuration file. Bugfix Cam Check CamCheck Report The images in the CamCheck report now have the correct format. Axis Bodycam Crash in BWC Connector An issue in the Axis BWC connector was fixed, which led to an unwanted crash during the export of the VMS configuration file. Bugfix Axis Bodycam Incorrect description of BWC Connector An issue in the installation of the Axis bodycam integration was fixed, which led to a wrong description of the approximation file. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video fixed in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video fixed in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video fixed in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video fixed in the Axis bodycam integration was fixed i	yfix <i>A</i>	Axis Bodycam	Misbehavior in saving video material	We fixed an issue, where a random number of bodycam plugins are not able to sucessfully save the respective video footage.
Bugfix Axis Bodycam Setup saving not possible We fixed an issue, where the G-Set setup was not saved successfully after a change of the Axis bodycam configuration. Bugfix Cam Check CamCheck Report The images in the CamCheck report now have the correct format. Bugfix Axis Bodycam Crash in BWC Connector An issue in the Axis BWC connector was fixed, which led to an unwanted crash during the export of the VMS configuration file. Bugfix Axis Bodycam Incorrect description of BWC Connector An issue in the installation of the Axis bodycam integration was fixed, which led to a wrong description of the approximately after a change of the Axis bodycam configuration. An issue in the Axis BWC connector was fixed, which led to an unwanted crash during the export of the VMS configuration file. Bugfix Axis Bodycam Incorrect description of BWC Connector An issue in the installation of the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video with the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video with the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video with the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video with the Axis bodycam integration was fixed.	yfix N	MBEG	Misbehavior in camera cycles	An issue with the MBEG plugin was fixed, which led to a wrong behaviour of camera cycles.
Bugfix Cam Check CamCheck Report The images in the CamCheck report now have the correct format. Bugfix Axis Bodycam Crash in BWC Connector An issue in the Axis BWC connector was fixed, which led to an unwanted crash during the export of the VMS configuration file. Bugfix Axis Bodycam Incorrect description of BWC Connector An issue in the installation of the Axis bodycam integration was fixed, which led to a wrong description of the apparate. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video	yfix F	Plugin	E4 Plugin - H.265 quality profile	Custom quality profiles for H.265 now work correctly with the E4 plugin.
Bugfix Axis Bodycam Crash in BWC Connector An issue in the Axis BWC connector was fixed, which led to an unwanted crash during the export of the VMS configuration file. Bugfix Axis Bodycam Incorrect description of BWC Connector An issue in the installation of the Axis bodycam integration was fixed, which led to a wrong description of the approximately afterwards. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video	jfix <i>F</i>	Axis Bodycam	Setup saving not possible	We fixed an issue, where the G-Set setup was not saved sucessfully after a change of the Axis bodycam configuration.
configuration file. Bugfix Axis Bodycam Incorrect description of BWC Connector An issue in the installation of the Axis bodycam integration was fixed, which led to a wrong description of the appartment. Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video	gfix (Cam Check	CamCheck Report	The images in the CamCheck report now have the correct format.
Bugfix Axis Bodycam Playback problem of video material An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video	jfix A	Axis Bodycam	Crash in BWC Connector	· · · · · · · · · · · · · · · · · · ·
	yfix <i>A</i>	Axis Bodycam	Incorrect description of BWC Connector	An issue in the installation of the Axis bodycam integration was fixed, which led to a wrong description of the applications afterwards.
Bugfiy Avia Badysam Missing vides material after hadysam use. An issue in the Avia hadysam integration was fixed, which lad to rendemly missing vides featage.	yfix A	Axis Bodycam	Playback problem of video material	An issue in the Axis bodycam integration was fixed, which led to a wrong behaviour during the playback of video footage.
Bugfix Axis Bodycam Missing video material after bodycam use An issue in the Axis bodycam integration was fixed, which led to randomly missing video footage.	yfix <i>F</i>	Axis Bodycam	Missing video material after bodycam use	An issue in the Axis bodycam integration was fixed, which led to randomly missing video footage.
Bugfix Axis Bodycam Missing video material after server restart An issue in the Axis bodycam integration was fixed, which led to missing video footage after a recent G-Core server restart.	jfix A	Axis Bodycam	Missing video material after server restart	An issue in the Axis bodycam integration was fixed, which led to missing video footage after a recent G-Core server restart.
Bugfix Axis Bodycam Partial .Net 5 Integration for Axis Bodycam Due to an issue with older .Net versions, the .Net 5 version was partially integrated into the service of the Axis but integration.	yfix <i>A</i>	Axis Bodycam	· · · · · · · · · · · · · · · · · · ·	Due to an issue with older .Net versions, the .Net 5 version was partially integrated into the service of the Axis bodycam integration.
Bugfix Axis Bodycam Stucked Video Processing An issue in the Axis bodycam integration was fixed, which led to stucked video processing due to a redudant uply video files.	yfix A	Axis Bodycam	Stucked Video Processing	An issue in the Axis bodycam integration was fixed, which led to stucked video processing due to a redudant upload of video files.
Bugfix G-Core V6 G-Core installers We removed the styling from all G-Core installers due to problems in virtual environments / remote desktop installer.	,		G-Core installers	·

G-Core 6.1.0 System Requirements

SERVER:		CLIENT:	SDK: same requirement as the client
Storage for video	minimal: 50 GB, recommended at least 1 TB		
Storage for installation	minimal 50 GB, recommended: 128 GB	Storage for installation	minimal: 5 GB
RAM	min. 8 GB	RAM	min. 8 GB
CPU recommendation	see table below	CPU recommendation	see table below
Network Interface	min. 1 Gbit/s	Network Interface	min. 1 Gbit/s
Operating System	Windows 10 LTSB (1607), (1809), Windows Server 2016 (1607) Windows Server 2019 (1809)	Operating System	Windows 10 LTSB (1607), (1809), Windows Server 2016 (1607) Windows Server 2019 (1809)
Microsoft SQL Server	SQL Server 2014, SQL Server 2014 Express (Microsoft SQL Server Express supports 1 physical processor, 1 GB memory, and 10 GB storage)		
Microsoft .Net Version	.NET Framework 3.5 & .NET Framework 4.6.1	Microsoft .Net Version	.NET Framework 3.5 & .NET Framework 4.6.1
Graphics card	Intel graphics card (only for hardware decoding)	Graphics card	Intel graphics card

HARDWARE RECOMMENDATION:

We recommend the following CPU and Intel graphic drivers. We cannot guarantee functionality and performance without the use of recommended drivers. GPU drivers are like any software, each new release can introduce performance and stability issues. If a problem appears at one point, we recommend to try to use a tested version.

Product Collection	Code Name	Processor Number	Processor Graphics	Graphic Driver Version	Graphic Driver Version
4th generation Intel® Core™ i3, i5, i7 Processors	Haswell	Core i3-4330 Processor 3.5Ghz Core i5-4570S Processor 2.9Ghz Core i7-4770S Processor 3.1GHz	Intel® HD Graphics 4600	15.36.28.4332 (Win 8.1)	20.19.15.4377 (Win 10 1607)
6th generation Intel® Core™ i3, i5, i7 Processors	Skylake	Core i3- 6100TE Processor 2.7Ghz Core i5- 6500 Processor 3.2Ghz Core i7- 6700 Processor 3.4Ghz	Intel® HD Graphics 530	21.20.16.4639 (Win 8.1)	
7th Generation Intel® Core™ i3, i5, i7 Processors	Kaby Lake	Core i3- 7100TE Processor 3.9Ghz Core i5- 7500 Processor 3.4Ghz Core i7- 7700 Processor 3.6Ghz	Intel® HD Graphics 630	21.20.16.4678 (Win 10 1607)	26.20.100.7263 (Win 10 1809, Legacy) 26.20.100.7584 (Win 10 1809, DCH)

These drivers are not necessarily part of the G-Core installer. You may find an updated list in our Knowledge Base: https://support.geutebrueck.com/de/search/detail/intel-gpu-driver-recommendation.html

GEUTEBRUCK

G-Core 6.1.0 System Requirements

Product Collection	Code Name	Processor- Number	Processor Graphics	Graphic Driv er Version	Graphic Driver Version
8. Generation Intel® Core™ i3, i5, i7 Processors 9. Generation Intel® Core™ i3, i5, i7,i9 Processors	Coffee Lake	Core 8000 Serie Processor Core 9100 Serie Processor Core 9500 Serie Processor Core 9700 Serie Processor Core 9900K Serie Processor Xeon E-2244G Processor	Intel® UHD Graphics 630 Intel® UHD Graphics 630 Intel® UHD Graphics 630 Intel® UHD Graphics 630 Intel® UHD Graphics 630 Intel® UHD Graphics 630 Intel® UHD Graphics 630 Intel® UHD Graphics 630		25.20.100.6519 DHC (Win 10 1809) 27.20.100.9168 DHC (Win Serv 2019 1809)
Intel® Celeron® Processors J Serie	Gemini Lake	Intel Celeron J4105 2.5 Ghz	Intel® UHD Graphics 600	25.20.100.6582 (Win 10 1607)	
Intel® Xeon® Processors E3 v6 Familie	Kaby Lake	Intel XEON E31275V6	Intel® HD Graphics P630	21.20.16.4678 (Win Serv 2016)	

These drivers are not necessarily part of the G-Core installer. You may find an updated list in our Knowledge Base: https://support.geutebrueck.com/de/search/detail/intel-gpu-driver-recommendation.html

ONVIF S Profile and T Profile Features



Geutebrück supports the following features of the Onvif S Profile (Client) and the Onvif T Profile (Client) :

Features			
General		S	Т
System Settings		С	С
User Authentication	WS-Username Token	М	
	Digest Authentication	М	М
User Handling		С	С
Query Services and Capabilities		М	М
Device Discovery		С	М
Network Configuration		С	М
Zero configuration		С	
IP Address Filtering		С	
NTP		С	С
Media Profile Configuration		С	С
Media Transport (1)	RTP/UDP	М	М
(1)	RTP/RTSP/HTTP/ TCP	М	М
	RTP/RTSP/ HTTPS/TCP	М	С
	RTP/UDP Multicast	С	С
Video			
Video Streaming	MJPEG	М	
	MPEG4	С	
	H.264	С	М
	H.265		М
Video Encoder Configuration		М	М
Video Source Configuration		С	С
Media Profile Streaming Ready out of the box		С	М
Video Streaming	RTSP/RTP	М	М
Imaging Settings			М

Features			
Events	S	Т	
Event Handling	Pull-point	М	М
	Base-notification	М	
Motion Alarm Events			М
Tampering Event			М
Audio			
Audio Streaming	G.711	С	С
	AAC	С	С
	G726	С	С
Audio Encoder		С	С
Configuration			C
PTZ			
PTZ Move	Absolute	С	М
	Continuous	С	М
	Relative	С	
PTZ Presets		С	С
PTZ - Home Position		С	С
PTZ Configuration		С	С
Additional			
Relay Outputs		С	С
Auxiliary commands		С	С
Focus Control			С
Digital Inputs			С
Metadata Configuration		С	С
Metadata Streaming			С
(1) Client must support a Function List use the fol M: Mandatory C: Conditional			P.

= Feature is supported.

= Feature is not supported.

Technical alterations reserved.