

GEUTEBRÜCK

Release Notes for E2 Firmware V1.12.0.27

Changes Notes

[INFO]

- The limited firmware V1.12.11.2, V1.12.14.5, V1.12.16.7 have been incorporated in this release.

[ADD]

- Added Autorun function in IPX3802SV. (V1.12.16.7)
- Added polygon privacy masking function. (V1.12.16.7)

[IMPROVE]

- Patched the vulnerabilities CVE-2015-3200, CVE-2018-19052, CVE-2019-10956.
- Increased the URL Length for HTTP Notification from 48 to 128. (V1.12.14.5)
- Moved the Repositioning menu of the IPX3802SV from Setup>PTZ>Repositioning to Setup>Video&Audio>Repositioning. (V1.12.14.5)
- Added the function to set the PTZ Preset Name in IPX3802SV. It was not changed by user. (V1.12.14.5)
- Improved the accuracy of event snapshots. (V1.12.14.5)
- Improved to maintain the last setting position when turning the camera off and on. (V1.12.14.5)
- Improved the current PTZ coordinates to be seen on IPX3802SV web. (V1.12.16.7)

[MODIFY]

- Removed the heater control web UI for the ITC4500QD/VD thermal camera. (V1.12.11.2)

[BUG]

- Fixed the memory leak that the specific daemon causes.
- Fixed the issue that the firmware update occasionally fails. (V1.12.12.6)
- Fixed a security vulnerability in web CGI. (V1.12.14.5)
- Fixed the problem that the setting is not applied when saving VCA PTZ Profile. (V1.12.16.7)
- Fixed the problem where VCA BIA and VCA profile are not properly linked. (V1.12.16.7)