GEUTEBRÜCK

G-SIM

Software Version 8.4.2

Release Notes

G-SIM 8.4.2

Software	Type	Short description	Details
Bugfix	OpCon	Login from OpCon to G-SIM Server on slow WAN connections takes too long	Due to high load on login caused by loading the user photos the OpCon needed a long time to login. The mechanism was changed so that the login is much faster.
Bugfix	OpCon	Timestamps between G-SIM OpCon and Windows Time are shifting	Under some circumstances it could happen that the viewer OSD time information is shifting from the original windows time.
Bugfix	OpCon	Drag and Drop of Alarms into Viewer is not working	The drag and drop mechanism did not allow the operator to drop a G-SIM Alarm into the viewer cell area.
Bugfix	Opcon	Connection limit in TC Viewer	The connection limit counter for connections used by the Transcoding viewer was not working accordingly and showed the "Site in used" message.
Bugfix	OpCon	TMR: Incorrect user login	When logging in with a second user during the runtime of the OpCon it could happen that not all privileges where applied accordingly to the both logged-in users.
Bugfix	OpCon	G-SIM Tour runs although it was closed before	When opening a tour where not all cameras are working, cloding the tour and opening a single camera in the same viewer the next camera from the guard tour was played.
Bugfix	OpCon	TMR: Wrong text	The OpCon showed the wrong text information when a second user logged in.
Bugfix	ManCon	Primary camera flag is not set in Alarm Simulator	The configuration of the primary camera flag in an G-SIM alarm was not recognized in the Alarm Simulator when opening an alarm instance
Bugfix	OpCon	Reference Images aren't removed from the system after deleting a camera or media source	Old reference images which are outdated where not deleted from the G-SIM folders even if they are not required anymore. The mechnism was changed to delete unnecessary reference images.
Bugfix	ManCon	Check dual channels displayed in grid if it should display 1 or 2 channels	The dual channel configuration for Transcoding server channels was not always working accordingly
Bugfix	OpCon	OSD Scaling Issue	The OSD was under special circumstances not scaling correctly between two lines
Bugfix	OpCon	Jump to previos event does not sow OSD in failover state	Then the system is in a failover state and the show previous motion button was pressed the viewer could not find the previous event.

G-SIM 8.4.2

Bugfix	Installer	G-SIM installation proceeds in case .NET 3.5 included in installer is ot installed for some reason	The G-SIM Installer did sometimes proceed with the installation even if the dotnet dependency installation failed before.