GEUTEBRüCK

GeViScope

Software Version 7.8.975.55

Fixed Bugs List

Software	Type	Short description	Detailed description
Bug fix	ANPR	Number plate templates 'E' and 'H' added	Number plate templates for E (electric) and H (historic) cars now added.
Bug fix	CamCheck	CamCheck did not display all pictures of cameras in reports	CamCheck did not display all pictures of cameras in reports on low bandwidth/high traffic/slow cameras and high camera count.
Bug fix	Client	ReExport-Blocking function added in GscDBI	ReExport-Blocking function for GeViScope GBF-files in the GscDBI.dll implemented.
Bug fix	Client	Access violation in GscView after sending action 'ViewerShowAlarmByType ()'	GSCView showed access violation after sending action 'ViewerShowAlarmByType()'. With Windows 7 GSCView crashed. This bugs has been fixed.
Bug fix	Client	Privacy functions added to GeViScope	The privacy functions have been added to GeViScope. It is able now to export GeViScope footage with 'privacy masking' out of G-SIM OpCon.
Bug fix	Client	Action 'ViewerShowAlarmByType' didn't work	Action ViewerShowAlarmByType didn't work. Bug fixed now.
Bug fix	GscView	PlayMode was not set correctly for 'Server Master'	PlayMode was not set correctly for 'Server Master' when synchronizing viewers over several Servers. This bug has been corrected.
Bug fix	IP Cameras	ONVIF Plugin: No more PTZ after CameraRawOutput action	If using camera PNS ECO 3SP56-12X and sending commands via CameraRawOutput action, there was no more movement possible with PTZ.
Bug fix	IP Cameras	Potential security flaw eliminated	Potential security flaw - exploit: Send 2GB XML file to OnVIF Plugin might result in crash and potential access to system. This security flaw has been eliminated.
Bug fix	IP Cameras	Temporary installation error with older TopLine firmware versions	Older FW version could somtimes cause installing failures. In the TopLine-Plugin the latest 3.15.1 FW version will be used now.
Bug fix	SDK	Hanging behaviour in MediaPlayer	Hanging behaviour in MediaPlayer fixed when ConnectDB was called.

Bug fix	Server	New "Security Management Systems" actions	GeViScope now offers a generic set of actions to be used for the integration of security management systems for better understanding and easier reaction on the events notified: SMS DoorAction SMS CardReaderAction SMS SystemErrorAction SMS OperatorAction SMS SystemAction SMS IOAction SMS IntercomAction SMS ViewerAction
Bug fix	Server	New actions to be used with G-SIM	New actions VCChangeMapByName and VCMapChanged created to be used with G-SIM.
Bug fix	Server	GeViScope server crashed when used by OpCon	GeViScope server crashed when used by OpCon. This bug has been fixed.
Bug fix	Server	Sometimes CPU-Usage 100% with action "SetTestPictureMode"	If the Action "SetTestPictureMode" was sent to GscServer using an RTSP-Plugin, the CPU-Usage could increase up to 100%. This is solved now.
Bug fix	Server	E2_IPC Sync lost will not be updated by CustomAction (1, "refreshstates")	E2_IPC Sync lost will not be updated by CustomAction (1, "refreshstates"). This behaviour has been corrected.
Bug fix	Server	Gsc user lost his rights after setup changes	Gsc user lost his rights after setup changes. Now he keeps his rights as long as he is logged in and even if the setup has been changed.
Bug fix	VAM	Sometimes OutOfMemory-Exception while old data check	Deleting old data on daily check could result in OutOfMemory exception when a large dataset was found. This is now fixed.

GEUTEBRÜCK GmbH

Im Nassen 7-9 | D-53578 Windhagen
Tel. +49 (0)2645 137-0 | Fax-999
info@geutebrueck.com

www.geutebrueck.com

Technische Änderungen vorbehalten.

Technical alterations reserved.

Sous réserve des modifications.

Suministro sujeto a modificaciones técnicas o disponibilidad.