GeViScope 7.8.974.52

Software	Type	Short description	Detailed description
Information	GeViScope	Update the recorder software when using the new G-SIM Software release	When G-SIM NVR failover is used, it is important to have all GeViScope and G-Scope recorders updated to the currently released software.
New Feature	ANPR	New countries in G-Tect/ANPR	The following new country code templates have been added to the license plate recognition program ANPR: United Kingdom, Iceland, Liechtenstein, Macedonia, Montenegro, Serbia, Bosnia and Herzegovina
Bug fix	GscServer		During failover state the restart of GeViScope Server did not always work well. Sometimes the server terminated instead of restart. This bug is fixed now.
Bug fix	RTSP-Client		A camera started communication via RTSP without sending any picture. Here no 'sync lost' signal was sent. This bug is fixed now.
Bug fix	VAM		Import of vehicle data from csv file failed if permissions are included in the file (granted, denied). This bug is fixed now.