

# GEUTEBRÜCK

## G-Core

Software Version 4.0.2

---

### Release Notes

## G-Core Release 4.0.2

Software	Type	Short description	Detailed description
Bugfix	VCA	VCA Bridge FW v4	This version now supports VCA Bridge with firmware V4, where all settings are done on the Web UI of the VCA bridge. Also, alarm rectangles of the objects that triggered an alarm are displayed in G-View when an alarm is being viewed.
Bugfix	SAM	Softdongle - Improve Binding Robustness	This G-Core SAM version contains an improved softdongle that introduces a more robust behaviour on systems with changing network configuration. An existing softdongle can continued to be used, when new options are requested, we recommend to create a new SLR request file, so the dongle can be upgraded to the new version.
Bugfix	G-View	Search or Jumo forwards with daylight saving time	Searching for a specified time or jumping forward during the missing hour when switching to daylight savings time did not return the right results. This has been fixed.
Bugfix	IMEX	Destination folder in IMEX	Fixed the issue related to not being able to add a valid path in G-Core IMEX editor.
Bugfix	G-Set	Rename AD and SV Templates	Added "Rename Template" in context menu for AD or SV templates.
Bugfix	VAM	Changes to vehicles are not saved	GCoreVAM did not save the settings done in the vehicles list. This is now fixed.
Bugfix	Server	Server crashes by ring buffer settings	The number of ring buffers for the GCore server can be adjusted in the Windows-Registry if special settings require this. If a setup contains higher values than this adjusted ring buffer count, i.e. because the windows registry value has been deleted or has been modified to a lower value, an access violation or memory corruption will occur in the PLC of the GCore server. This has been fixed.
Bugfix	IP cameras	ONVIF / Bosch Plugin - Disable GNG settings	In the Onvif and Bosch Plugin, the option "Disable GNG settings" stays checked in some cases after unchecking. This has been fixed.
Bugfix	G-View	Multimonitor menu	There was a bug, that multimonitor setting were not displayed correctly in the Profilemanager when switching to another form and back again.

---

Technical alterations reserved.

**GEUTEBRÜCK GmbH**

Im Nassen 7-9 | D-53578 Windhagen | Tel. +49 (0)2645 137-0 | Fax-999 | E-mail: [info@geutebrueck.com](mailto:info@geutebrueck.com) | Web: [www.geutebrueck.com](http://www.geutebrueck.com)