

NSX - Firmware Release Note

Updated Software Version:

gb20190716NSX (please refer to the upgrade instructions in the zip-folder)

Reference Software Version gb20170906NSX

Applied Model:

EBC-3139, EBC-3140, EBC-3141, EFD-3245, EFD-3255, EFD-3247, EFD-3257, EFD-3248, EFD-3258, EFD-3261, EFD-3266, EFD-3131 EWPC-3210, EWPC-3220, EWPC-3212, EWPC-3222, EWPC-3213, EWPC-3223, EWPC-3270, EWPC-3271

Change Log

- (1) IP address get from DHCP Server should not be changed with firmware upgrade.
- (2) ClientID (DHCP code 61) default as MAC.
- (3) Add host name (code 12) to DHCP, default as MAC.
- (4) Users could change host name through webpage.