

GEUTEBRÜCK

GeViScope

Software Version 7.8.975.59

Fixed Bug List

GeViScope 7.8.975.59

Software	Type	Short description	Detailed description
Bug fix	Vulnerability	Cross-Site-Scripting Issue in web statistics	XSS (Cross-Site-Scripting) Issue in web statistics resolved. Browser will now not return the invalid filename requested on web statistics pages on port 12003. This prevents XSS issues, which might occur in combination with old browsers, because scripts embedded in URLs will not be executed (a minor issue since login works only locally on GeViScope / re_reporter and admin credentials must be known).

Technical alterations reserved.

GEUTEBRÜCK GmbH

Im Nassen 7-9 | D-53578 Windhagen | Tel. +49 (0)2645 137-0 | Fax-999 | E-mail: info@geutebrueck.com | Web: www.geutebrueck.com